



# HYUNDAI Technical Service Bulletin

Group	CHASSIS
Number	09-ST-003
Date	MAY, 2009
Model	ALL GENESIS COUPE

Subject  
**GENESIS COUPE POWER STEERING FLUID TYPE**

<b>CIRCULATE TO:</b>	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY MGR	<input type="checkbox"/> SALES MANAGER

**DESCRIPTION:**

This bulletin provides notification of the power steering fluid change for ALL Genesis Coupes from PSF-3 to Pentosin CHF 202.

**NOTE:** If replacing the power steering oil pump assy, completely drain the power steering fluid and replace w/ Pentosin CHF202 (ref Shop Manual Sec. ST-19)

**AFFECTED VEHICLES:**

- Model: ALL GENESIS COUPE vehicles
- Effective vehicle production date: December 15, 2008 ~

**PARTS INFORMATION:**

Description	Qty	Previous	New
Power steering fluid	0.9 US qt.	PSF-3	Pentosin CHF 202 P/N 00232-19017